```
FILE 'REGISTRY' ENTERED AT 14:26:01 ON 01 JUL 2004
                E 12033-89-5
L1
              1 SEA ABB=ON PLU=ON 12033-89-5/RN
                D IDE
     FILE 'HCAPLUS' ENTERED AT 14:50:11 ON 01 JUL 2004
           1719 SEA ABB=ON PLU=ON PHOTORESIST(L)(ASH#### OR OXIDAT###### OR
L2
                OXIDIS? OR OXIDIZ?)
         339475 SEA ABB=ON PLU=ON HIGH TEMPERATURE
L.3
                           PLU=ON PURE(W)(O2 OR OXYGEN)
PLU=ON PHOTORESIST OXIDATION
           2795 SEA ABB=ON
L4
L5
              8 SEA ABB=ON
             66 SEA ABB=ON PLU=ON PHOTORESIST (2A) OXIDATION
L6
              O SEA ABB=ON PLU=ON PHOTORESIST(2A)OXIDIS?
L7
L8
             60 SEA ABB=ON PLU=ON PHOTORESIST (2A) OXIDIZ?
            127 SEA ABB=ON PLU=ON RESIST(2A)OXIDIZ?
L9
L10
             O SEA ABB=ON
                            PLU=ON RESIST (2A) OXIDIS?
            540 SEA ABB=ON PLU=ON RESIST(2A)OXIDAT?
L11
     FILE 'REGISTRY' ENTERED AT 14:52:10 ON 01 JUL 2004
L12
             27 SEA ABB=ON PLU=ON O2/MF
     FILE 'HCAPLUS' ENTERED AT 14:52:29 ON 01 JUL 2004
           1269 SEA ABB=ON PLU=ON L12(L)(PURE OR PURITY)
L13
         754636 SEA ABB=ON PLU=ON (INCREAS#### OR RAIS##### OR ELEVAT######
L14
                OR HIGH####) (2A) TEMPERATURE
1.15
              O SEA ABB=ON PLU=ON (L2 OR (L5 OR L6 OR L7 OR L8 OR L9 OR L10
                OR L11)) AND (L4 OR L13) AND (L3 OR L14)
L16
              4 SEA ABB=ON PLU=ON (L2 OR (L5 OR L6 OR L7 OR L8 OR L9 OR L10
                OR L11)) AND (L4 OR L13)
L17
              1 SEA ABB=ON PLU=ON L16 AND (TEMPERATURE OR THERMAL### OR
                ANNEAL#### OR RTP OR RTA)
                D ALL HITSTR
L18
              3 SEA ABB=ON PLU=ON L16 NOT L17
                D ALL HITSTR TOT
     FILE 'STNGUIDE' ENTERED AT 14:55:41 ON 01 JUL 2004
     FILE 'HCAPLUS' ENTERED AT 14:56:51 ON 01 JUL 2004
L19
            197 SEA ABB=ON PLU=ON RESISTS(L)O2
             11 SEA ABB=ON PLU=ON (L4 OR (L13 OR L14)) AND L19
L20
L21
             11 SEA ABB=ON PLU=ON L20 NOT (L17 OR L18)
L22
             11 SEA ABB=ON PLU=ON L21 AND (HEAT#### OR THERMAL##### OR
                ANNEAL###### OR TEMPERATURE)
                D ALL HITSTR TOT
     FILE 'STNGUIDE' ENTERED AT 14:58:23 ON 01 JUL 2004
     FILE 'INSPEC' ENTERED AT 15:00:39 ON 01 JUL 2004
                E O2/CHI
            510 SEA ABB=ON PLU=ON ("O2 BIN"/CHI OR "O2 EL"/CHI) AND (PURE OR
L23
                100) (2W) (O2 OR O OR OXYGEN)
L24
              O SEA ABB=ON PLU=ON L23 AND (OXIDAT####### OR OXIDIS? OR
                OXIDIZ?) (2A) (RESIST OR PHOTORESIST)
L25
             65 SEA ABB=ON PLU=ON (OXIDAT####### OR OXIDIS? OR OXIDIZ?)(2A)(
                RESIST OR PHOTORESIST)
T.26
             22 SEA ABB=ON PLU=ON (OXIDAT####### OR OXIDIS? OR OXIDIZ?)/TI
                AND (RESIST OR PHOTORESIST)/TI
L27
              O SEA ABB=ON PLU=ON L23 AND L26
            419 SEA ABB=ON PLU=ON O SUB 2
L28
                           PLU=ON (L23 OR L24 OR L25 OR L26) AND L28
PLU=ON (L23 OR L24 OR L25 OR L26) AND ASH####
L29
             0 SEA ABB=ON
L30
             10 SEA ABB=ON
              4 SEA ABB=ON PLU=ON L30 AND PURE(W) (OXYGEN OR O OR O2)
L31
                D ALL TOT
```

```
FILE 'JICST-EPLUS' ENTERED AT 15:05:06 ON 01 JUL 2004
            308 SEA ABB=ON PLU=ON PURE(W)(O OR O2 OR OXYGEN)
L32
L33
            121 SEA ABB=ON PLU=ON (O OR O2 OR OXYGEN)(3A)(ASH### OR RESIST
                OR PHOTORESIST)
L34
              1 SEA ABB=ON PLU=ON L32 AND L33
                D ALL
             58 SEA ABB=ON PLU=ON (L32 OR L33) AND ASHING
L35
             23 SEA ABB=ON PLU=ON L35 AND (TEMPERATURE OR THERMAL#### OR
L36
                HEAT#### OR ANNEAL### OR RTA OR RTP)
L37
              1 SEA ABB=ON PLU=ON L36 AND PRESSUR######
                D ALL
L38
          22405 SEA ABB=ON PLU=ON OXYGEN/CT
             17 SEA ABB=ON PLU=ON L35 AND L38
L39
L40
              6 SEA ABB=ON PLU=ON L36 AND L39
              2 SEA ABB=ON PLU=ON L39 AND PRESSURE
L41
L42
              6 SEA ABB=ON
                            PLU=ON (L40 OR L41) NOT (L34 OR L37)
                D ALL TOT
     FILE 'STNGUIDE' ENTERED AT 15:09:07 ON 01 JUL 2004
     FILE 'JICST-EPLUS' ENTERED AT 15:10:28 ON 01 JUL 2004
             10 SEA ABB=ON PLU=ON ((L35 OR L36) OR L39) NOT PLASMA
9 SEA ABB=ON PLU=ON L43 NOT (L34 OR L37 OR (L40 OR L41))
L43
L44
                D ALL TOT
```

FILE 'REGISTRY' ENTERED AT 10:21:21 ON 01 JUL 2004 L130 $$27\ S\ O2/MF$$

```
FILE 'HCAPLUS' ENTERED AT 10:21:37 ON 01 JUL 2004
L131 364427 S L130
                E ASHING/CT
                E E3+ALL/CT
L132
            410 S L131 AND E3
L133
           2018 S L131 AND PHOTORESIST
L134
           20 S L131 AND PHOTO RESIST
             41 S L131 AND (OXIDI? OR OXIDAT?) (2A) RESIST
L135
L136
            163 S L131 AND (ASH OR ASHED OR ASHING) (2A) RESIST
L137
            13 S L133-136 AND HIGH PRESSURE
L138
             0 S L133-136 AND ULTRAHIGH PRESSURE
L139
             0 S L133-136 AND ULTRAHIGH (2A) PRESSURE
L140
             34 S L133-136 AND HIGH####(2A)PRESSURE
             0 S L137-140 AND L130(L) PURE
3 S L137-140 AND L130(L) GAS
L141
L142
L143
             0 S L137-140 AND L130(L)GASEOUS
L144
             0 S L137-140 AND L130(L)VAPOR
L145
             0 S L137-140 AND L130(L) VAPOUR
L146
             1 S L137-140 AND PURE
L147
              4 S L142 OR L146
L148
            17 S L137 OR L147
```

=>

01jul04 09:05:44 User259284 Session D2824.2

| File | | 1969-2004/Jun W3 |
|------------|----------|--|
| | (c) 2004 | Institution of Electrical Engineers |
| Set | Items | Description |
| S1 | 148550 | |
| S2 | 19796 | |
| S3 | 2223 | |
| S4 | 10 | S3 AND (ASH??? OR PHOTORESIST? OR PHOTOMASK? OR PHOTO??(W) - |
| 0 . | | ASK?? OR RESIST??)) |
| S5 | 52 | (OXIDIS? OR OXIDIX? OR OXIDAT??????) (2N) (RESIST OR RESISTS |
| | OR | PHOTORESIST????) |
| S6 | 0 | 3AND5 |
| s7 | 1 | S2 AND S5 |
| S8 | 11 | S4 OR S7 |
| S9 | 17 | O2(2N)(GAS OR GASES OR GASEOUS OR GASSES OR VAPOR?????? OR |
| | VAI | POUR????) |
| S10 | 3020 | O(1W)2(2N)(GAS OR GASES OR GASEOUS OR GASSES OR VAPOR?????? |
| | OF | R VAPOUR????) |
| S11 | 4486 | OXYGEN(2N)(GAS OR GASES OR GASEOUS OR GASSES OR VAPOR?????? |
| | | R VAPOUR????) |
| S12 | 1184 | ,,,, |
| S13 | | S10:S12 AND S2 |
| S14 | 1 | S13 AND (OXIDI?????? OR OXIDAT?????? OR ASH???? OR REMOV??- |
| | | ?)(3N)(PHOTORESIST?? OR RESIST OR RESISTS) |
| S15 | 4 | S12 AND (OXIDI?????? OR OXIDAT?????? OR ASH???? OR REMOV??- |
| | | ?)(3N)(PHOTORESIST?? OR RESIST OR RESISTS) |
| S16 | 4 | S15 NOT S14 |
| ? | | |